

AERMOTOR

DEAN BENNETT SUPPLY CO

Toll Free : 800 - 621 - 4291

Repair Parts

9 - 1 - 09

Page 56

Parts Orders Less than \$ 200

Net

Parts Orders \$ 200 thru \$ 500

-15% Disc

Parts Orders Over \$ 500

-20% Disc

REPAIR PARTS FOR CURRENT MODEL #802 & OLDER MODEL #702 AERMOTOR WINDMILLS

Description	Part #	(X) 6 Ft	(A) 8 Ft	(B) 10 Ft	(D) 12 Ft	(E) 14 Ft	(F) 16 Ft
Vane Spring	28	\$ 21.00	\$ 26.00	\$ 48.00	\$ 84.00	\$ 138.00	\$ 190.00
Outer Band of Wheel	34	28.75	39.25	80.50	119.75	234.75	306.00
Inner Band of Wheel	35	12.75	24.25	37.00	63.25	86.25	129.00
Narrow U-Bolt for Vane	44	11.00	13.00	13.00	16.00	18.00	29.00
Wide U-Bolt for Vane	46	11.00	13.00	13.00	18.00	26.00	44.00
14' Long Wood Pump Pole	51	No Longer Furnished - Buy Locally					
Connector - Pump Pole to Well Rod	62	24.00	24.00	31.00	41.00	57.00	90.00
Set of Pump Pole Splice Straps	82	24.00	24.00	30.00	38.00	53.00	64.00
Sail w/sail tie #17	100	33.50	41.50	74.75	97.75	138.00	189.00
Sail Rib	101	7.00	9.00	12.00	17.00	21.00	31.00
#802 Domestic Pull Rod	171	62.75	66.00	90.25	159.50	288.25	476.00
#702 Import Pull Rod	FR171	59.50	62.75	85.75			
Furl Handle Assembly	243-1/2	45.00	45.00	64.00	90.00	96.00	142.00
Oil Ring	507	9.00	10.00	11.00	14.00	15.00	17.00
Pitman Guide w/#588 & 2-#508R	508	45.00	56.00	70.00	154.00	286.00	326.00
Pitman Guide Rivet	508R	1.00	3.00	4.00	5.00	6.00	7.00
Pivot Bolt for Tail Bone	510	22.00	25.00	40.00	63.00	92.00	130.00
Spring for Spout Washer	517	3.00	3.00	5.00	6.00	7.00	8.00
Oil Collector	520	12.00	13.00	16.00	18.00	28.00	38.00
Split Washer	521	10.00	11.00	13.00	15.00	20.00	23.00
Shaft for Guide Wheel w/Cotters	522	14.00	22.00	31.00	42.00	81.00	120.00
Guide Wheel	523	32.00	39.00	50.00	82.00	118.00	157.00
Furl Link w/Cotter Pin	527	9.00	10.00	15.00	17.00	24.00	29.00
Furl Arms w/Cotter Pins (pair)	528	25.00	33.00	40.00	65.00	76.00	95.00
Furl Arms w/Cotters (pair) Long	528-1/2	26.00	34.00	42.00	66.00	79.00	98.00
Furl Arms w/Cotters (pair) X-Long	528-3/4	N/A	36.00	44.00	68.00	81.00	100.00
Helmet w/hardware	560	186.00	203.50	234.50	317.00	533.50	612.00
Nut for 588	565	5.00	5.00	5.00	6.00	6.00	7.00
Steel Washer for Table	576	2.00	3.00	5.00	7.00	9.00	10.00
Locknut for Top of Mastpipe	578	10.00	15.00	24.00	35.00	48.00	56.00
Lockwasher for Top of Mastpipe	579	4.00	5.00	7.00	8.00	9.00	11.00
Vane Spring Holder	580	10.00	14.00	17.00	31.00	34.00	38.00
Tailbone Casting	585	39.00	46.00	82.00	95.00	129.00	163.00
Stud for Pitman Guide	588	5.00	5.00	5.00	8.00	9.00	11.00
Pump Rod Yoke w/Cotter Pin	608	53.00	57.00	63.00	121.00	169.00	250.00
Furl Lever Complete - 4 Post	609S	97.00	120.00	170.00	226.00	376.00	456.00
Pin for 608 Yoke	610	6.00	7.00	9.00	10.00	12.00	16.00
Upper Furl Ring w/o Arms	613-1/2	82.00	88.00	101.00	151.00	229.00	330.00
Lower Furl Ring 4 Post Split	614S	39.00	42.00	63.00	81.00	101.00	124.00
Bolt w/ Cotter Pin	622	6.00	7.00	9.00	12.00	14.00	15.00

PRICES SHOWN IN DARKER BOLD TYPE ARE NORMAL DENVER STOCK REPAIR PARTS

REPAIR PARTS QUALIFY FOR \$ 1,000.00 FREIGHT PREPAID ORDERS